

## **SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS**

## **SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS**

## **SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS**

Document Name	DP98	FT23 (FT-1)	LF01 (D-1)	LF02 (D-2)	LF03 (D-3)	LF04 (D-4)	LF05 (D-5)	LF06 (D-6)	LF07 (D-7)	LF08 (D-8)	LF09 (D-9)	LF12 (D-12)	LF13 (D-13)	LF59	OT56 (NS-2)	OT82	PL81	RW17 (RD-1)	SD15 (D-16)	SD16 (D-17)	SD24 (IS-1)	SD25 (IS-2)	SD26 (IS-3)	SD27 (IS-4)	SD28 (IS-5)	SD29 (IS-6)	SD30 (IS-7)	SD31 (IS-8)	SD40 (SP-4)	SD52 (NS-1)	SD73	SS10 (D-10)	SS18 (S-1)	SS19 (S-3)	SS21 (S-6)	SS22 (S-7)	SS34 (ST-34)	SS35	SS42 (SP-6)	SS43/55 (SP-7)	SS44 (SP-8)
Annual Report of Groundwater Sampling (3/96)	X																																								
SS19 No Further Remedial Action Plan (4/96)																														X											
OU6 Proposed Plan (4/96)			X	X	X																								X												
SS57 NFA (4/96)																																									
ST47 NFA (4/96)																																									
ST65 NFA (4/96)																																									
Environmental Cleanup Plan Phase II (4/96)																	X																								
OU6, SD15 Treatability Study Workplan (5/96)																																									
Groundwater Modeling Report for ST43/55 (5/96)																																	X								
Environmental Monitoring Plan (5/96)	X	X		X	X		X									X	X	X													X										
Sampling & Analysis of Ship Creek (5/96)																																									
OU4 Bioventing/Soil Monitoring Report (6/96)	X																															X									
OU5 RD Title II Services WP (6/96)																																	X								
OU6, WP14 Treatability Study WP (6/96)																																									
OU6, WP14 90% Design (6/96)																																									
Follow-On Investigations/Treatability Studies WP (6/96)																																									
OU1 Groundwater Sampling (7/96)									X	X						X	X	X																							
OU2 Groundwater Sampling (7/96)																																									
OU5 Groundwater Sampling (7/96)																																									
OU6, LF04 Treatability Study WP (7/96)						X																																			
OU6, POL Line Investigation WP (7/96)																									X																
SERA Phase I Groundwater Sampling (7/96)																																	X								
SERA Phase II Groundwater Sampling (7/96)																																									
BW Water Level Monitoring Technical Memorandum (7/96)																																									
OU6, LF02 Environmental Cleanup Plan (8/96)					X																																				
ST43/55, Bioventing Treatability Study-100% Design (8/96)																																	X								
Sampling & Analysis of Ship Creek (8/96)																																									
OU4 Groundwater Sampling (8/96)	X																								X																
OU6 Groundwater Sampling (8/96)						X		X																X																	
OU3, SS21 Biotreatability Study (9/96)																																X									
OU6, LF02 Quality Project Plans						X																																			
OU6, SD15 Treatability Study 100% Design (9/96)																									X																
OU6, LF02 RA WP (10/96)							X																																		
OU6, SD15 Treatability Excavation Report (10/96)																								X																	
SERA Phase III Groundwater Sampling (10/96)																																									
Final Results of SERA Phase III Investigation (10/96)																																									
OU2, ST41 Soil Mapping Report (11/96)																																									
ST69 NFA (11/96)																																									
Final Site Closure Report for ST71 (11/96)																																									
Sampling & Analysis of Ship Creek (11/96)																																									
OU1 Groundwater Sampling (11/96)									X	X						X	X	X																							
OU2 Groundwater Sampling (11/96)																																									
SERA Phase I Groundwater Sampling (11/96)																																		X							
SERA Phase II Groundwater Sampling (11/96)																																									
OU4 Groundwater Sampling (12/96)					X																			X																	
OU5 Groundwater Sampling (12/96)																																									
Area Under Evaluation Informal Technical Information Report (1/97)																																									
OU3 ROD (1/97)																									X		X							X							

## SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS

Document Name	DP98	FT23 (FT-1)	LF01 (D-1)	LF02 (D-2)	LF03 (D-3)	LF04 (D-4)	LF05 (D-5)	LF06 (D-6)	LF07 (D-7)	LF08 (D-8)	LF09 (D-9)	LF12 (D-12)	LF13 (D-13)	LF59	OT56 (NS-2)	OT82	PL81	RW17 (RD-1)	SD15 (D-16)	SD16 (D-17)	SD24 (IS-1)	SD25 (IS-2)	SD26 (IS-3)	SD27 (IS-4)	SD28 (IS-5)	SD29 (IS-6)	SD30 (IS-7)	SD31 (IS-8)	SD40 (SP-4)	SD52 (NS-1)	SD73	SS10 (D-10)	SS18 (S-1)	SS19 (S-3)	SS21 (S-6)	SS22 (S-7)	SS34 (ST-34)	SS35	SS42 (SP-6)	SS43/55 (SP-7)	SS44 (SP-8)
OU6 and Source Area SS19 ROD (1/97)				X	X	X																																			
OU6 - LF02 Quality Project Plan (1/97)				X																																					
BW Water Level Monitoring Technical Memorandum (1/97)	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X										
OU3 - SS21 RD (3/97)																																									
OU1 - LF59 Technical Report (4/97)																																									
OU6 RD/RA Scope of Work (4/97)			X	X																																					
ST77 NFA (5/97)																																									
ST79 NFA (5/97)																																									
Annual Report of Groundwater Sampling (5/97)	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X										
OU3 RD Fact Sheet (6/97)																																									
OU4 Bioventing Remediation Monitoring Annual Report (6/97)	X																																								
PL81 Pipeline Removal Design (9/97)																																									
OU1 Groundwater Sampling (9/97)							X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X									
OU2 Groundwater Sampling (9/97)																																									
OU4 Groundwater Sampling (9/97)	X																																								
OU5 Groundwater Sampling (9/97)																																									
OU6 Groundwater Sampling (9/97)		X	X	X																																					
SERA Phase I Groundwater Sampling (9/97)																																									
SERA Phase II Groundwater Sampling (9/97)																																									
SERA Phase III Groundwater Sampling (9/97)																																									
OU1 Groundwater Sampling (12/97)							X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X									
OU2 Groundwater Sampling (12/97)																																									
OU4 Groundwater Sampling (12/97)	X																																								
OU5 Groundwater Sampling (12/97)																																									
OU6 Groundwater Sampling (12/97)		X	X	X																																					
SERA Phase I Groundwater Sampling (12/97)																																									
SERA Phase II Groundwater Sampling (12/97)																																									
SERA Phase III Groundwater Sampling (12/97)																																									
LF04 Debris Removal Treatability Study Report (1/98)							X																																		
Management Action Plan (3/98)	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X									
BW Water Level Monitoring Biannual Technical Memorandum (3/98)	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X										
OU1 Quarterly Progress Report (3/98)								X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X									
OU2 Quarterly Progress Report (3/98)																																									
OU3 Quarterly Progress Report (3/98)																																									
OU4 Quarterly Progress Report (3/98)	X																																								
OU5 Quarterly Progress Report (3/98)																																									
OU6 North Quarterly Progress Report (3/98)								X																																	
OU6 South Quarterly Progress Report (3/98)		X	X																																						
OU2 Quarterly Progress Report (6/98)									X																																
OU3 Quarterly Progress Report (6/98)										X																															

## **SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS**

## SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS

Document Name	DP98	FT23 (FT-1)	LF01 (D-1)	LF02 (D-2)	LF03 (D-3)	LF04 (D-4)	LF05 (D-5)	LF06 (D-6)	LF07 (D-7)	LF08 (D-8)	LF09 (D-9)	LF12 (D-12)	LF13 (D-13)	LF59	OT56 (NS-2)	OT82	PL81	RW17 (RD-1)	SD15 (D-16)	SD16 (D-17)	SD24 (IS-1)	SD25 (IS-2)	SD26 (IS-3)	SD27 (IS-4)	SD28 (IS-5)	SD29 (IS-6)	SD30 (IS-7)	SD31 (IS-8)	SD40 (SP-4)	SD52 (NS-1)	SD73	SS10 (D-10)	SS18 (S-1)	SS19 (S-3)	SS21 (S-6)	SS22 (S-7)	SS34 (ST-34)	SS35	SS42 (SP-6)	SS43/55 (SP-7)	SS44 (SP-8)
OU4 Quarterly Progress Report (3/99)		X																																							
OU5 Quarterly Progress Report (3/99)																																									
OU6 North Quarterly Progress Report (3/99)					X																																				
OU6 South Quarterly Progress Report (3/99)				X X																																					
DP98 Quarterly Progress Report (3/99)	X																																								
SS83 Quarterly Progress Report (3/99)																																									
SERA Quarterly Progress Report (3/99)																																			X						
SD15 High-Vacuum Extraction (HVE) System Annual Report (5/99)																																									
OU5 Wetland Remediation System 1998 Annual Report (6/99)																																									
BW Environmental Monitoring Plan (6/99)					X	X X		X			X X X							X		X													X								
1998 Annual Report of Groundwater Sampling Vol I of II (6/99)					X	X X		X			X X X							X		X												X									
1998 Annual Report of Groundwater Sampling Vol II of II (6/99)					X	X X		X			X X X							X		X											X										
OU1 Quarterly Progress Report (6/99)						X	X				X X X																														
OU2 Quarterly Progress Report (6/99)																																									
OU3 Quarterly Progress Report (6/99)																																									
OU4 Quarterly Progress Report (6/99)	X																																								
OU5 Quarterly Progress Report (6/99)																																		X							
OU6 North Quarterly Progress Report (6/99)						X																																			
OU6 South Quarterly Progress Report (6/99)				X X																													X								
DP98 Quarterly Progress Report (6/99)	X																																								
SS83 Quarterly Progress Report (6/99)																																			X						
SERA Quarterly Progress Report (6/99)																																									
SD25 and FT23 Site Closure WP, SAP, and HSP - Revision 1 (8/99)		X																																							
OU5 Environmental HSP (8/99)																																									
OU5 Remediation & Monitoring WP (8/99)																																									
SD15 SAP and HSP (8/99)																																									
OU4 Groundwater Sampling (8/99)		X																																							
OU5 Groundwater Sampling (8/99)																																									
OU6 Groundwater Sampling (8/99)				X X														X	X																						
Taxiway "N" Groundwater Sampling (8/99)							X	X										X	X																						
OU1 Quarterly Progress Report (9/99)							X	X				X X X																													
OU2 Quarterly Progress Report (9/99)																																									
OU3 Quarterly Progress Report (9/99)																			X															X							
OU4 Quarterly Progress Report (9/99)	X																		X X X X X X X X													X									
OU5 Quarterly Progress Report (9/99)																			X														X								
OU6 North Quarterly Progress Report (9/99)					X													X																							
OU6 South Quarterly Progress Report (9/99)				X X																													X								
DP98 Quarterly Progress Report (9/99)	X																																								
SS83 Quarterly Progress Report (9/99)																																									
SERA Quarterly Progress Report (9/99)																																		X							
OU1 Groundwater Sampling (9/99)					</td																																				

## **SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS**

## **SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS**

## **SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS**

## SUMMARY OF PAST ENVIRONMENTAL RESTORATION PROGRAM INVESTIGATIONS

Note: \*ST43/55 is the same source area as SS43/55.